
Readme/Installationsanleitung für DIGSI V4.84 Hotfix 3

Neuerungen und Änderungen

Folgende Fehler werden mit dem DIGSI V4.84 Hotfix 3 behoben:

IEC 61850-Station kann nicht aktualisiert werden.

Die Probleme beim Aktualisieren von IEC 61850-Stationen mit bis zu 150 Teilnehmern sind behoben.

Systemvoraussetzungen

Zusätzlich zu den in der Produktinformation von DIGSI V4.84 genannten Systemanforderungen benötigt dieses Hotfix ein Minimum von 2 GB RAM. Siemens empfiehlt eine Speicherkonfiguration von 3 GB. Des Weiteren empfiehlt Siemens den virtuellen Speicher auf 2 GB zu erhöhen.

Hinweise zur Benutzung/Einschränkungen

DIGSI V4.84, DIGSI V4.84 HF1 oder DIGSI V4.84 HF2 muss auf Ihrem Rechner installiert sein.

Kompatibilität

DIGSI V4.84 Hotfix 3 darf nur mit DIGSI V4.84, DIGSI V4.84 HF1 oder DIGSI V4.84 HF2 eingesetzt werden.

Lieferumfang

Das DIGSI V4.84 Hotfix 3 beinhaltet folgende Dateien/Ordner:

```
| DIGSIUpdate.bat  
| GNL_DIGSI-V4.84_HF3_Readme.pdf  
+---DIGSI4  
| Iec2Map.dll          V 2.12.01  
| Siprotec.dll         V 2.14.03  
|  
| \---MANAGER  
|   \---S7BIN  
|     p7diiedx.dll     V 4.84.14  
|     Siprotec.dll     V 2.14.03
```

Installation

1. Stellen Sie sicher, dass DIGSI V4.84, DIGSI V4.84 HF1 oder DIGSI V4.84 HF2 auf dem Rechner installiert ist.
2. Beenden Sie DIGSI V4.84, bevor Sie das DIGSI V4.84 Hotfix 3 installieren.
3. Entpacken Sie die Datei in ein lokales Verzeichnis auf ihrem Rechner. Behalten Sie dabei die Unterverzeichnisse bei, siehe „Lieferumfang“.
4. Starten Sie das Installationsscript **DIGSIUpdate.bat**. Dies installiert den Hotfix in Ihre lokale DIGSI 4-Installation.
5. Löschen Sie die entpackten Dateien.

Hinweise zur Installation

So erkennen Sie, dass das DIGSI V4.84 Hotfix 3 installiert ist:

Öffnen Sie den "Eigenschaften"-Dialog der installierten Dateien mit dem MS Windows-Explorer, öffnen Sie die Registerkarte "Version" und überprüfen Sie, ob die Version angezeigt wird, die in „Lieferumfang“ angegeben ist, siehe oben.

Deinstallation

Sie können das DIGSI V4.84 Hotfix 3 nicht separat deinstallieren.

Hotline-Kontakt

Falls Sie Probleme bei der Installation und Benutzung des DIGSI V4.84 Hotfix 3 haben, wenden Sie sich bitte an das Siemens Customer Support Center.

Tel: +49 (180) 524-8437

Fax: +49 (180) 524-2471

E-Mail: support.ic@siemens.com

FAQ: <http://www.siemens.com/energy-support>

Readme/Installation Instructions for DIGSI V4.84 Hotfix 3

New Features and Modifications

The DIGSI V4.84 Hotfix 3 eliminates the following problems:

Unable to update IEC 61850 station.

Problems with updating IEC 61850 stations with up to 150 communicators have been resolved.

System Requirements

Additional to the system requirements mentioned in the product information of DIGSI V4.84, this Hotfix requires a minimum of 2 GB RAM. Siemens recommends a memory configuration of 3 GB. Furthermore Siemens recommends increasing the virtual memory to 2 GB.

Comments to Usage and Restrictions

DIGSI V4.84, DIGSI V4.84 HF1 or DIGSI V4.84 HF2 must be installed on your computer.

Compatibility

DIGSI V4.84 Hotfix 3 can only be used to update DIGSI V4.84, DIGSI V4.84 HF1 or DIGSI V4.84 HF2.

Contents of the Consignment

DIGSI V4.84 Hotfix 3 contains following files/folders:

```
| DIGSIUpdate.bat  
| GNL_DIGSI-V4.84_HF3_Readme.pdf  
+---DIGSI4  
| Iec2Map.dll          V 2.12.01  
| Siprotec.dll         V 2.14.03  
|  
| \---MANAGER  
|   \---S7BIN  
|     p7diiedx.dll    V 4.84.14  
|     Siprotec.dll    V 2.14.03
```

Installation

1. Make sure that DIGSI V4.84, DIGSI V4.84 HF1 or DIGSI V4.84 HF2 is installed on your computer.
2. Please close DIGSI V4.84 before you install the DIGSI V4.84 Hotfix 3.
3. Unzip the files in a local folder of your computer. Keep the folder structure as it is in the ZIP archive, see "Contents of the Consignment".
4. Execute the installation script **DIGSIUpdate.bat**. This will install the hotfix into your local DIGSI 4 installation.
5. Delete the unzipped files.

Remarks to Installation

How to recognize that DIGSI V4.84 Hotfix 3 has been installed:

Open the "Properties" of the installed files in MS Windows-Explorer, open the "Version" tab and check if it shows the version that is listed in "Contents of the Consignment", see above.

Uninstallation

You cannot uninstall the DIGSI V4.84 Hotfix 3 separately.

Support

If you have problems with installation and usage of the DIGSI V4.84 Hotfix 3, please contact the Siemens Customer Support Center.

Tel: +49 (180) 524-8437

Fax: +49 (180) 524-2471

E-Mail: support.ic@siemens.com

FAQ: <http://www.siemens.com/energy-support>